

Activity Description	Completed Date	Activity Code	Created at	Created by	Defect Chainage End	Defect Chainage Start	Status	Wbscode	Claim Number	Sims No	Job No	Work Order	Road Code	Completed Amount	Comment	Chainage End	Chainage Start	Contract	Schedule
Remove Unauthorised Signs		8B42410	15/12/2022	dzfinch	50.67	49.09	Scheduled	1890			1706550	2354665	202		Remove 2 unauthorised signs from TMR furniture Beaudesert Nerang rd at Crane cr & Bartlett av.	52.14		0 CN-11008 Yr 4	08
(PC) Other Furniture Repairs	29/12/2022	8B55900	5/12/2022	dzfinch	51.76	51.76	Claimed	1980	46		1703138	2355398	202	1239	Reinstall unstable bus zone sign Price st NB LHS just before White st intersection. Sign face ok, 1 x 50mm post approx 2600mm high from footing.	52.14		0 CN-11008 Yr 4	08
(PC) Other Furniture Repairs	23/11/2022	8B55900	15/11/2022	dzfinch	48.73	48.73	Claimed	1980	45		1697226	2351886	202	1902.61	Reinstall unstable QG infrastructure info sign Beaudesert Nerang rd WB LHS just before McLaren rd intersection. Sign face, post & post flange all good, req new dyna bolt installation.	52.14		0 CN-11008 Yr 4	08
(PC) Incident Response	28/10/2022	6B45300	28/10/2022	wzmathe	47.61	47.61	Claimed	1590	44	45074	1692462	2348868	202	1560.16	IR 28/10/2022 19:15 Called by SCTMC(#45074) To Locate and make safe large pothole Beaudesert-Nerang Rd (Mt Nathan Rd) EB side street Birdlife Court	52.14		0 CN-11008 Yr 4	06
(PC) Incident Response	28/10/2022	6B45300	28/10/2022	igrood	47.61	47.61	Claimed	1590	44	44952	1692399	2348829	202	2769.14	IR 28/10/2022 10:54 Called by SCTMC(#44962) Locate and make safe large pothole Beaudesert-Nerang Rd (Mt Nathan Rd) EB side street Birdlife Court	52.14		0 CN-11008 Yr 4	06
(PC) Surface Debris Removal	21/10/2022	8B13500	21/10/2022	nzhowla	45.76	45.76	Claimed	1820	44		1689479	2345978	202	1152.4	Removal of dumped tyres in a culvert on Nerang Beaudesert Rd chainage 45.760 day works shoulder closure	52.14		0 CN-11008 Yr 4	08
(PC) Other Roadside Work	25/09/2022	8B42900	7/09/2022	dzfinch	44.61	44.61	Claimed	1900	43		1675524	2340605	202	1028.33	Enquiry #3861, remove graffiti from backside of guide sign Beaudesert Nerang rd EB LHS just before Nathan Valley rd. TC LHS closure gm crew day work aluminium spray paint	52.14		0 CN-11008 Yr 4	08
(PC) Other Furniture Repairs	8/10/2022	8B55900	7/09/2022	dzfinch	48.341	48.341	Claimed	1980	44		1675391	2343972	202	2321.9	Reinstall knocked down warning signs post Beaudesert Nerang rd WB LHS just after McLaren rd. Top sign good (couple small marks don't affect functionality), 1 x WB-158, 1 x 50mm post approx 3200mm high from footing. TC LHS and merge lane closure gm crew day work rapid set	52.14		0 CN-11008 Yr 4	08
(PC) Clearing	29/09/2022	8B40510	31/08/2022	dzfinch	44.73	44.65	Claimed	1850	43		1673862	2343305	202	2712.68	Clear vegetation obscuring vision of 2 separate warning signs Beaudesert Nerang rd EB LHS basically opp Nathan Valley rd. Several small trees req branches cut back, TC stop go lane closures gm crew day work pole saw chainsaw	52.14		0 CN-11008 Yr 4	08
(PC) Other Roadside Work	29/08/2022	8B42900	25/08/2022	dzfinch	51.77	51.72	Claimed	1900	42	35553	1672209	2337446	202	1520.8	Sims #35553, remove knocked down tree Beaudesert Nerang rd centre median between Tabbings st & White st intersections. Poss use contractor with chipper or gm crew with chainsaws & vehicle large enough to fit material for removal, TC day work	52.14		0 CN-11008 Yr 4	08

Released under RTI Act

Job 1672209 DEFECT

<input type="checkbox"/> Claimed	
Priority	10
Due Date	-
Activity	8B42900 - (PC) Other Roadside Work
WBS	1900 - (PC) Other Roadside Work
Comment	Sims #35553, remove knocked down tree Beaudesert Nerang rd centre median between Tibbings st & White st intersections. Poss use contractor with chipper or gm crew with chain-saws & vehicle large enough to fit material for removal, TC day work
Stakeholder Req.	-
Schedule	08 - 22/23 SCH M8B
Contract	CN-11008 Yr 4 - GC - Gold Coast RMC 2022/2023
Work Order	WO2337446 - Green crew <input type="checkbox"/> Expired 29/08/2022 - 30/08/2022
Claim	42 <input type="checkbox"/> Finalized
Created	25/08/2022 by dzfinch
Approved	29/08/2022 by scnorri
Completed	29/08/2022 by adcoxon
Reference	-
Job Type	DEFECT
Source System	AMMS

SIMS Info	
SIMS Number	35553


Defect Location	
Road	202 - BEAUDESERT - NERANG ROAD
Chainage	51.72 - 51.77 (0.05 km)
Carriageway	2 - Primary Through Divided in Gazettal
Lane	M - 3rd Lane in Centre of Undivided Cway (G)
Road Tier	5
Road Category	Cat C

Defect Details	
Defect	RE2_S - Litter on road reserve - Schedule with Mowing Category: 400 - Roadside Assets
Size	-
Fault Cause	-
Fault Indication	-

SAP Info	
SAP Ref. ID	7011210 1900 2772
SAP Network No.	7011210

Claim Details	
Quantity	NR <input type="checkbox"/>
Amount	<input type="checkbox"/>

Dissections				
Date	Resource	Qty	Rate	Total
29/08/2022	Plant VMS0001 - RMC - VMS Ute (Dry Hire)	NR		
29/08/2022	Labour TC0002 - RMC - Traffic Controller Only (Penalty)			
29/08/2022	Labour TC0001 - RMC - Traffic Controller Only (Day)			
29/08/2022	Labour 103001 - RMC - 10300 (S or C) - Construction Worker (Day)			
29/08/2022	Labour 103001 - RMC - 10300 (S or C) - Construction Worker (Day)			
29/08/2022	Labour 103001 - RMC - 10300 (S or C) - Construction Worker (Day)			
29/08/2022	Labour 103001 - RMC - 10300 (S or C) - Construction Worker (Day)			
29/08/2022	Labour 103001 - RMC - 10300 (S or C) - Construction Worker (Day)			
29/08/2022	Plant VMS0002 - RMC - VMS Truck (Dry Hire)			



Priority Details	
Priority	10 <input type="checkbox"/>
Corp. Weighting	-
Field Weighting	-
Road Cat. Score	-
Risk Score	-
Response Time	-
Response Due Date	-
Inspection Due Date	-



Released under RTI

29/08/2022	Plant TRK0003 - RMC - Truck (Dry Hire) <9.5T pay load
29/08/2022	Plant TMA0001 - RMC - Truck TMA - (Dry Hire)
29/08/2022	Plant TRK0002 - RMC - Truck (Dry Hire) <3.5T pay load



Released under RTI - DTMR

Job 1673862 DEFECT

Claimed

Priority: 10

Due Date: -

Activity: 8B40510 - (PC) Clearing

WBS: 1850 - (PC) Clearing

Comment: Clear vegetation obscuring vision of 2 separate warning signs Beaudesert Nerang rd EB LHS basically opp Nathan Valley rd. Several small trees req branches cut back, Tc stop go lane closures gm crew day work pole saw chainsaw

Stakeholder Req: -

Schedule: 08 - 22/23 SCH M8B

Contract: CN-11008 Yr 4 - GC - Gold Coast RMC 2022/2023

Work Order: WO2343305 - NO NAME 30/09/2022 - 01/10/2022

Claim: 43

Created: 31/08/2022 by dzfinch

Approved: 30/09/2022 by myspenc

Completed: 29/09/2022 by adcoxon

Reference: -

Job Type: DEFECT

Source System: AMMS

SIMS Info

SIMS Number: -

Defect Location

Road: 202 - BEAUDESERT - NERANG ROAD

Chainage: 44.65 - 44.73 (0.08 km)

Carriageway: 1 - Primary Through Undivided

Lane: E - L.H. Road Shoulder

Road Tier: 5

Road Category: Cat C

Defect Details

Defect: NH2.S - Vegetation height on shoulders is greater than value shown. Category: 400 - Roadside Assets

Size: -

Fault Cause: -

Fault Indication: -

SAP Info

SAP Ref. ID: 7011210-1850-3138

SAP Network No.: 7011210


Claim Details

Quantity	Estimated	Completed
NR		

Amount:

Dissections

Date	Resource	Qty	Rate	Total
29/09/2022	Labour 103001 - RMC - 10200 (\$ or C) - Construction Worker (Day)	NR		
29/09/2022	SubContract MIS001 - RMC - Sub Contractor as per Invoice			
29/09/2022	Plant VMS0001 - RMC - VMS Ute (Dry Hire)			
29/09/2022	Labour TC0002 - RMC - Traffic Controller Only (Penalty)			
29/09/2022	Labour TC0001 - RMC - Traffic Controller Only (Day)			
29/09/2022	SubContract MIS001 - RMC - Sub Contractor as per Invoice			
29/09/2022	Plant TRK0003 - RMC - Truck (Dry Hire) <9.5T pay load			



Priority Details

Priority: 10

Corp. Weighting: -

Field Weighting: -

Road Cat. Score: -

Risk Score: -

Response Time: -

Response Due Date: -

Inspection Due Date: -



Released under RTI



Job 1675391 DEFECT

Claimed

Priority: 9

Due Date: 07/10/2022 07:59

Activity: 8B55900 - (PC) Other Furniture Repairs

WBS: 1980 - (PC) Other Furniture Repairs

Comment: Reinstall knocked down warning signs post Beaudesert Nerang rd WB LHS just after McLaren rd. Top sign good (couple small marks don't affect functionality), 1 x WB-15B, 1 x 50mm post approx 3200mm high from footing. TC LHS end merge lane closure gm crew day work rapid set

Stakeholder Req. -

Schedule: 08 - 22/23 SCH M8B

Contract: CN-11008 Yr 4 - GC - Gold Coast RMC 2022/2023

Work Order: WO2343972 - Other furniture repairs 08/10/2022 - 09/10/2022

Claim: 44

Created: 7/09/2022 by dzfinch

Approved: 8/10/2022 by akkels

Completed: 8/10/2022 by adcoxon

Reference: -

Job Type: DEFECT

Source System: AMMS

SIMS Info

SIMS Number: -

Defect Location

Road: 202 - BEAUDESERT - NERANG ROAD

Chainage: 48.341 km

Carriageway: 3 - Primary Through Divided against Gazettal

Lane: E - L.H. Road Shoulder

Road Tier: 5

Road Category: Cat C

Defect Details

Defect: S13_S - Sign is on a noticeable lean (greater than 15 degrees)
Category: 500 - Road Furniture Assets

Size: -

Fault Cause: -

Fault Indication: -

SAP Info

SAP Ref. ID: 7011210 1980 3225


SAP Network No.: 7011210

Claim Details

	Estimated	Completed
Quantity	NR	
Amount		

Dissections

Date	Resource	Qty	Rate	Total
08/10/2022	Labour 103002 - RMC - 10300 (P or CN) - Construction Worker (Penalty)	NR		
08/10/2022	Labour 103002 - RMC - 10300 (P or CN) - Construction Worker (Penalty)			
08/10/2022	Labour 103002 - RMC - 10300 (P or CN) - Construction Worker (Penalty)			
08/10/2022	Plant VMS0001 - RMC - VMS Ute (Dry Hire)			
08/10/2022	Labour TC0002 - RMC - Traffic Controller Only (Penalty)			
08/10/2022	Labour 103002 - RMC - 10300 (P or CN) - Construction Worker (Penalty)			
08/10/2022	Labour 103002 - RMC - 10300 (P or CN) - Construction Worker (Penalty)			
08/10/2022	Labour 103002 - RMC - 10300 (P or CN) - Construction Worker (Penalty)			
08/10/2022	Labour 103002 - RMC - 10300 (P or CN) - Construction Worker (Penalty)			



Priority Details

Priority: 9

Corp. Weighting: -

Field Weighting: -

Road Cat. Score: -

Risk Score: -

Response Time: 30 days

Response Due Date: 07/10/2022 07:59

Inspection Due Date: 08/10/2022 07:59



Released Under RTI

08/10/2022	Labour 103002 - RMC - 10300 (P or CN) - Construction Worker (Penalty)
08/10/2022	Material MAS001 - RMC - Rapid Set Concrete - 20kg Bag
08/10/2022	Material PIP001 - RMC - Gal Steel Post - 50mm NB
08/10/2022	Plant VMS0002 - RMC - VMS Truck (Dry Hire)
08/10/2022	Plant TRK0003 - RMC - Truck (Dry Hire) <9.5T pay load
08/10/2022	Plant TMA0001 - RMC - Truck TMA - (Dry Hire)
08/10/2022	Plant TRK0003 - RMC - Truck (Dry Hire) <9.5T pay load



Released under RTI - DURING

Job 1675524 DEFECT

<input type="button" value="Claimed"/>	
Priority	9
Due Date	07/10/2022 11:09
Activity	8B42900 - (PC) Other Roadside Work
WBS	1900 - (PC) Other Roadside Work
Comment	Enquiry #3861, remove graffiti from backside of guide sign Beaudesert Nerang rd EB LHS just before Nathan Valley rd. TC LHS closure gm crew day work aluminium spray paint
Stakeholder Req.	-
Schedule	08 - 22/23 SCH M8B
Contract	CN-11008 Yr 4 - GC - Gold Coast RMC 2022/2023
Work Order	WO2340605 - Green Crew <input type="button" value="Expired"/> 25/09/2022 - 26/09/2022
Claim	43 <input type="button" value="Finalized"/>
Created	7/09/2022 by dzfinch
Approved	25/09/2022 by gapinso
Completed	25/09/2022 by adcoxon
Reference	-
Job Type	DEFECT
Source System	AMMS
SIMS Info	
SIMS Number	-


Defect Location	
Road	202 - BEAUDESERT - NERANG ROAD
Chainage	44.61 km
Carriageway	1 - Primary Through Undivided
Lane	E - L.H. Road Shoulder
Road Tier	5
Road Category	Cat C

Defect Details	
Defect	RG3 S - Any other graffiti. Category: 400 - Roadside Assets
Size	-
Fault Cause	-
Fault Indication	-

SAP Info	
SAP Ref. ID	7011210-1900-3074
SAP Network No.	7011210

Claim Details	
Quantity	NR
Amount	

Dissections				
Date	Resource	Qty	Rate	Total
25/09/2022	Labour 103002 - RMC - 10300 (P or CN) - Construction Worker (Penalty)			
25/09/2022	Labour 103002 - RMC - 10300 (P or CN) - Construction Worker (Penalty)			
25/09/2022	Labour 103002 - RMC - 10300 (P or CN) - Construction Worker (Penalty)			
25/09/2022	Labour 103002 - RMC - 10300 (P or CN) - Construction Worker (Penalty)			
25/09/2022	Plant VMS0001 - RMC - VMS Ute (Dry Hire)			
25/09/2022	Labour TC0002 - RMC - Traffic Controller Only (Penalty)			
25/09/2022	Plant VMS0002 - RMC - VMS Truck (Dry Hire)			
25/09/2022	Plant TMA0001 - RMC - Truck TMA - (Dry Hire)			
25/09/2022	Plant TRK0003 - RMC - Truck (Dry Hire) <9.5T pay load			



Priority Details	
Priority	9 <input type="button" value="Summary"/>
Corp. Weighting	-
Field Weighting	-
Road Cat. Score	-
Risk Score	-
Response Time	30 days
Response Due Date	07/10/2022 11:09
Inspection Due Date	08/10/2022 11:09



Released Under RTI

25/09/
2022 Plant TRK0003 - RMC -
Truck (Dry Hire) <9.5T
pay load



Released under RTI - DTMR

Job 1689479 DEFECT

<input type="button" value="Claims"/>	
Priority	11
Due Date	-
Activity	8B13500 - (PC) Surface Debris Removal
WBS	1820 - (PC) Surface Debris Removal
Comment	Removal of dumped tyres in a culvert on Nerang Beaudesert Rd chainage : 45.760 day works shoulder closure
Stakeholder Req.	-
Schedule	00 - 22/23 SCH M8B
Contract	CN-11008 Yr 4 - GC - Gold Coast RMC 2022/2023
Work Order	WO2345978 - Veg crew <input type="button" value="Expired"/>
Claim	44 <input type="button" value="Finalized"/>
Created	21/10/2022 by nzhowla
Approved	21/10/2022 by nzhowla
Completed	21/10/2022 by adcoxon
Reference	-
Job Type	DEFECT
Source System	AMMS
SIMS Info	
SIMS Number	-

Defect Location

Road	202 - BEAUDESERT - NERANG ROAD
Chainage	45.76 km
Carriageway	2 - Primary Through Divided in Gazettal
Lane	E - L.H. Road Shoulder
Road Tier	5
Road Category	Cat C

Defect Details

Defect	EA6_N - Surface Debris Removal - Non-hazardous & Programable Category: 100 - Sealed Surfaces
Size	0 mm
Fault Cause	-
Fault Indication	-

SAP Info


SAP Ref. ID	7011210-1820-3364
SAP Network No.	7011210

Claim Details

	Estimated	Completed
Quantity	NR	
Amount		

Dissections

Date	Resource	Qty	Rate	Total
21/10/2022	Labour 103001 - RMC - 10300 (S or C) - Construction Worker (Day)	NR		
21/10/2022	Labour 103001 - RMC - 10300 (S or C) - Construction Worker (Day)			
21/10/2022	Labour 103002 - RMC - 10300 (P or CN) - Construction Worker (Penalty)			
21/10/2022	Labour 103002 - RMC - 10300 (P or CN) - Construction Worker (Penalty)			
21/10/2022	Plant TRK0003 - RMC - Truck (Dry Hire) <9.5T pay load			
21/10/2022	Plant TRK0002 - RMC - Truck (Dry Hire) <3.5T pay load			
24/10/2022	Material MIS001 - RMC - Various Materials as per Invoice			
24/10/2022	Material MIS001 - RMC - Various Materials as per Invoice			



Priority Details

Priority	11 <input type="button" value="Classification"/>
Corp. Weighting	-
Field Weighting	-
Road Cat. Score	-
Risk Score	-
Response Time	-
Response Due Date	-
Inspection Due Date	-



Released under RTI

Job 1692399 DEFECT

Comment

Priority: 3

Due Date: 28/10/2022 11:56

Activity: 6B45300 - (PC) Incident Response

WBS: 1590 - (PC) Incident Response

Comment: IR 28/10/2022 10:54 Called by SCTMC(#44962) Locate and make safe large pothole Beaudesert-Nerang Rd (Mt Nathan Rd) EB side street Birdlife Court

Stakeholder Req.: -

Schedule: 06 - 22/23 SCH M6B

Contract: CN-11008 Yr 4 - GC - Gold Coast RMC 2022/2023

Work Order: WO2348829 - Blue Crew
 28/10/2022 - 29/10/2022

Claim: 44

Created: 28/10/2022 by jgroad

Approved: 28/10/2022 by jgroad

Completed: 28/10/2022 by adcoxon

Reference: -

Job Type: DEFECT

Source System: AMMS

SIMS Info

SIMS Number: 44962

Defect Location

Road

Chainage

Carriageway

Lane

Road Tier

Road Category

Defect Details

Defect

Size

Fault Cause

Fault Indication

SAP Info

SAP Ref. ID

SAP Network No.

Claim Details

Quantity: NR

Amount

Dissections

Date	Resource	Quantity
28/10/2022	Labour 10 10300 (S o Construct (Day)	NR
28/10/2022	Plant VMS VMS Ute	
28/10/2022	Labour TC Traffic Con (Day)	
28/10/2022	Labour 10 10300 (S o Construct (Day)	
28/10/2022	Labour 10 10300 (S o Construct (Day)	
28/10/2022	Labour 10 10300 (S o Construct (Day)	
28/10/2022	Labour 10 10300 (S o Construct (Day)	
28/10/2022	Plant VMS VMS Truck	
28/10/2022	Material M Various M Invoice	
28/10/2022	Plant TMA Traffic M	



Priority Details

Priority: 3

Corp. Weighting: -

Field Weighting: -

Road Cat. Score: -

Risk Score: -

Response Time: 1 hours

Response Due Date: 28/10/2022 11:56

Inspection Due Date: 29/10/2022 11:56

Attachments

No attachments

Released under RTI

28/10/
2022 Plant TRK0003 - RMC -
Truck (Dry Hire) <9.5T
pay load

28/10/
2022 Plant TRK0003 - RMC -
Truck (Dry Hire) <9.5T
pay load



Released under RTI - DTMR

Job 1692462 DEFECT

<input type="checkbox"/> Claimed	
Priority	3
Due Date	28/10/2022 20:11
Activity	6B45300 - (PC) Incident Response
WBS	1590 - (PC) Incident Response
Comment	IR 28/10/2022 19:15 Called by SCTMC(#45074) To Locate and make safe large pothole Beaudesert-Nerang Rd (Mt Nathan Rd) EB side street Birdlife Court
Stakeholder Req.	-
Schedule	06 - 22/23 SCH M6B
Contract	CN-11008 Yr 4 - GC - Gold Coast RMC 2022/2023
Work Order	WO2348868 - NO NAME <input type="checkbox"/> Expired 28/10/2022 - 29/10/2022
Claim	44 <input type="checkbox"/> Finalized
Created	28/10/2022 by wzmathe
Approved	28/10/2022 by wzmathe
Completed	28/10/2022 by adcoxon
Reference	OCC
Job Type	DEFECT
Source System	AMMS
SIMS Info	
SIMS Number	45074

Defect Location

Road	202 - BEAUDESERT - NERANG ROAD
Chainage	47.61 km
Carriageway	1 - Primary Through Undivided
Lane	0 - All Lanes
Road Tier	5
Road Category	Cat C

Defect Details

Defect	ZA4.H - Any solid object, debris litter ect likely to cause a hazard. Size of object in any dimension Category: 900 - 900
Size	0 mm
Fault Cause	-
Fault Indication	-

SAP Info

SAP Ref. ID	7011210-1590-3446
SAP Network No.	7011210

Claim Details

	Estimated	Completed
Quantity	NR	
Amount		

Dissections

Date	Resource	Qty	Rate	Total
28/10/2022	Labour 103002 - RMC - 10300 (P or CN) - Construction Worker (Penalty)			
28/10/2022	Plant VMS0001 - RMC - VMS Ute (Dry Hire)			
28/10/2022	Labour TC0002 - RMC - Traffic Controller Only (Penalty)			
28/10/2022	Labour TC0002 - RMC - Traffic Controller Only (Penalty)			
28/10/2022	Labour 103002 - RMC - 10300 (P or CN) - Construction Worker (Penalty)			
28/10/2022	Labour 103002 - RMC - 10300 (P or CN) - Construction Worker (Penalty)			
28/10/2022	Labour 103002 - RMC - 10300 (P or CN) - Construction Worker (Penalty)			
28/10/2022	Labour 103002 - RMC - 10300 (P or CN) - Construction Worker (Penalty)			
28/10/2022	Plant VMS0002 - RMC - VMS Truck (Dry Hire)			
28/10/2022	Material MIS001 - RMC - Various Materials as per			



Priority Details

Priority	3 <input type="checkbox"/> Hazard
Corp. Weighting	-
Field Weighting	-
Road Cat. Score	-
Risk Score	-
Response Time	1 hours
Response Due Date	28/10/2022 20:11
Inspection Due Date	29/10/2022 20:11

Attachments

No attachments

Release Order RTI

28/10/2022 Plant TRK0003 - RMC - Truck (Dry Hire) <9.5T pay load

28/10/2022 Plant TRK0003 - RMC - Truck (Dry Hire) <9.5T pay load

28/10/2022 Plant TMA0001 - RMC - Truck TMA - (Dry Hire)



Released under RTI - DTMR

Job 1697226 DEFECT

Claimed

Priority: 9

Due Date: 15/12/2022 13:45

Activity: 8B55900 - (PC) Other Furniture Repairs

WBS: 1980 - (PC) Other Furniture Repairs

Comment: Reinstall unstable QG infrastructure info sign Beaudesert Nerang rd WB LHS just before McLaren rd intersection. Sign face, post & post flange all good, req new dyna bolt installation.

Stakeholder Req.:

Schedule: 08 - 22/23 SCH M8B

Contract: CN-11008 Yr 4 - GC - Gold Coast RMC 2022/2023

Work Order: WO2351886 - NO NAME Logged
23/11/2022 - 24/11/2022

Claim: 45 Finalized

Created: 15/11/2022 by dzfinch

Approved: 23/11/2022 by wzmathe

Completed: 23/11/2022 by adcoxon

Reference:

Job Type: DEFECT

Source System: AMMS

SIMS Info

SIMS Number:

Defect Location

Road: 202 - BEAUDESERT - NERANG ROAD

Chainage: 48.73 km

Carriageway: 1 - Primary Through Undivided

Lane: U - R.H. Road Shoulder

Road Tier: 5

Road Category: Cat C

Defect Details

Defect: S13 S - Sign is on a noticeable lean (greater than 15 degrees)
Category: 500 - Road Furniture Assets

Size: -

Fault Cause: -

Fault Indication: -

SAP Info

SAP Ref. ID: 7011210-1980-3707

SAP Network No.: 7011210


Claim Details

Quantity	Estimated	Completed
NR		

Amount:

Dissections

Date	Resource	Qty	Rate	Total
23/11/2022	Plant VMS0001 - RMC - VMS Use (Dry Hire)	NR		
23/11/2022	Plant VMS0002 - RMC - VMS Truck (Dry Hire)			
23/11/2022	Material PIP001 - RMC - Gal Steel Post - 50mm NB			
23/11/2022	Material MAS001 - RMC - Rapid Set Concrete - 20kg Bag			
23/11/2022	Labour 103002 - RMC - 10300 (P or CN) - Construction Worker (Penalty)			
23/11/2022	Labour 103001 - RMC - 10300 (S or C) - Construction Worker (Day)			
23/11/2022	Labour 103002 - RMC - 10300 (P or CN) - Construction Worker (Penalty)			
23/11/2022	Labour 103001 - RMC - 10300 (S or C) - Construction Worker (Day)			
23/11/2022	Labour 103002 - RMC - 10300 (P or CN) - Construction Worker (Penalty)			



Priority Details

Priority: 9 Claimed

Corp. Weighting: -

Field Weighting: -

Road Cat. Score: -

Risk Score: -

Response Time: 30 days

Response Due Date: 15/12/2022 13:45

Inspection Due Date: 16/12/2022 13:45



Released Under RTI

23/11/2022	Labour 103001 - RMC - 10300 (S or C) - Construction Worker (Day)
23/11/2022	Labour 103002 - RMC - 10300 (P or CN) - Construction Worker (Penalty)
23/11/2022	Labour 103001 - RMC - 10300 (S or C) - Construction Worker (Day)
23/11/2022	Labour 103002 - RMC - 10300 (P or CN) - Construction Worker (Penalty)
23/11/2022	Labour 103001 - RMC - 10300 (S or C) - Construction Worker (Day)
23/11/2022	Labour TC0002 - RMC - Traffic Controller Only (Penalty)
23/11/2022	Labour TC0001 - RMC - Traffic Controller Only (Day)
23/11/2022	Plant TRK0003 - RMC - Truck (Dry Hire) <9.5T pay load
23/11/2022	Plant TRK0003 - RMC - Truck (Dry Hire) <9.5T pay load



Released under RTI - DIMR

Job 1700841 DEFECT

<input type="checkbox"/> Claimed	
Priority	10
Due Date	-
Activity	8B41900 - (PC) Other Vegetation Control Works
WBS	1870 - (PC) Other Vegetation Control Works
Comment	Clear vegetation obscuring vision of geographical feature series guide sign Beaudesert Nerang rd EB LHS entry side of Mooyumbin ck just after Birribi av intersection. Several trees/shrubs req cutting back.
Stakeholder Req.	-
Schedule	<u>08 - 22/23 SCH M8B</u>
Contract	<u>CN-11008 Yr 4 - GC - Gold Coast RMC 2022/2023</u>
Work Order	<u>WO2361135 - Other Vegetation Control Works</u> <input type="checkbox"/> Inquired 16/02/2023 - 17/02/2023
Claim	<u>48</u> <input type="checkbox"/> Finalized
Created	25/11/2022 by dzfinch
Approved	16/02/2023 by akkels
Completed	16/02/2023 by adcoxon
Reference	-
Job Type	DEFECT
Source System	AMMS
SIMS Info	
SIMS Number	-

Defect Location

Road	202 - BEAUDESERT - NERANG ROAD
Chainage	51.31 - 51.36 (0.05 km)
Carriageway	2 - Primary Through Divided in Gazetted
Lane	E - L.H. Road Shoulder
Road Tier	5
Road Category	Cat C

Defect Details

Defect	NH2_S - Vegetation height on shoulders is greater than value shown. Category: 400 - Roadside Assets
Size	-
Fault Cause	-
Fault Indication	-

SAP Info


SAP Ref. ID	7011210 1870 4678
SAP Network No.	7011210

Claim Details

	Estimated	Completed
Quantity	<input type="text" value="NR"/>	<input checked="" type="checkbox"/>
Amount	<input type="text" value=""/>	<input checked="" type="checkbox"/>

Dissections

Date	Resource	Qty	Rate	Total
16/02/2023	Plant VMS0001 - RMC - VMS Use (Dry Hire)	NR		
16/02/2023	Labour 103001 - RMC - 10300 (S or C) - Construction Worker (Day)			
16/02/2023	Labour 103002 - RMC - 10300 (P or CN) - Construction Worker (Penalty)			
16/02/2023	Labour 103001 - RMC - 10300 (S or C) - Construction Worker (Day)			
16/02/2023	Labour 103002 - RMC - 10300 (P or CN) - Construction Worker (Penalty)			
16/02/2023	Labour 103002 - RMC - 10300 (P or CN) - Construction Worker (Penalty)			
16/02/2023	Labour 103001 - RMC - 10300 (S or C) - Construction Worker (Day)			
16/02/2023	Labour 103001 - RMC - 10300 (S or C) - Construction Worker (Day)			



Priority Details

Priority	10 <input type="text" value="submit"/>
Corp. Weighting	-
Field Weighting	-
Road Cat. Score	-
Risk Score	-
Response Time	-
Response Due Date	-
Inspection Due Date	-



Released under RTI

16/02/2023 Labour 103002 - RMC - 10300 (P or CN) - Construction Worker (Penalty)

16/02/2023 Labour 103001 - RMC - 10300 (S or C) - Construction Worker (Day)

16/02/2023 Labour 103002 - RMC - 10300 (P or CN) - Construction Worker (Penalty)

16/02/2023 Plant VMS0002 - RMC - VMS Truck (Dry Hire)

16/02/2023 Plant VMS0002 - RMC - VMS Truck (Dry Hire)

16/02/2023 Plant TRK0003 - RMC - Truck (Dry Hire) <9.5T pay load

16/02/2023 Plant TMA0001 - RMC - Truck TMA - (Dry Hire)

16/02/2023 Plant TRK0003 - RMC - Truck (Dry Hire) <9.5T pay load

16/02/2023 Labour 103002 - RMC - 10300 (P or CN) - Construction Worker (Penalty)

16/02/2023 Labour 103001 - RMC - 10300 (S or C) - Construction Worker (Day)

16/02/2023 Labour 103001 - RMC - 10300 (S or C) - Construction Worker (Day)

16/02/2023 Labour 103002 - RMC - 10300 (P or CN) - Construction Worker (Penalty)

16/02/2023 Labour TC0001 - RMC - Traffic Controller Only (Day)

16/02/2023 Labour TC0002 - RMC - Traffic Controller Only (Penalty)

16/02/2023 Labour 103002 - RMC - 10300 (P or CN) - Construction Worker (Penalty)

16/02/2023 Labour 103001 - RMC - 10300 (S or C) - Construction Worker (Day)



Released under RTI - DTMR

Job 1703138 DEFECT

Claims	
Priority	9
Due Date	04/01/2023 12:38
Activity	8B55900 - (PC) Other Furniture Repairs
WBS	1980 - (PC) Other Furniture Repairs
Comment	Reinstall unstable bus zone sign Price st NB LHS just before White st intersection. Sign face ok, 1 x 50mm post approx 2600mm high from footing.
Stakeholder Req.	-
Schedule	08 - 22/23 SCH M8B
Contract	CN-11008 Yr 4 - GC - Gold Coast RMC 2022/2023
Work Order	WO2355398 - Red Crew Expired 29/12/2022 - 30/12/2022
Claim	46 Finalised
Created	5/12/2022 by dzfinch
Approved	29/12/2022 by msmcdon
Completed	29/12/2022 by jgroad
Reference	-
Job Type	DEFECT
Source System	AMMS

SIMS Info	
SIMS Number	-


Defect Location	
Road	202 - BEAUDESERT - NERANG ROAD
Chainage	51.76 km
Carriageway	2 - Primary Through Divided in Gazzetal
Lane	E - L.H. Road Shoulder
Road Tier	5
Road Category	Cat C

Defect Details	
Defect	S13_S - Sign is on a noticeable lean (greater than 15 degrees) Category: 500 - Road Furniture Assets
Size	-
Fault Cause	-
Fault Indication	-

SAP Info	
SAP Ref. ID	7011210-1980-4091
SAP Network No.	7011210

Claim Details	
	Estimated Completed
Quantity	NR !
Amount	!

Dissections				
Date	Resource	Qty	Rate	Total
29/12/2022	Material MAS001 - RMC - Rapid Set Concrete - 20kg Bag	NR		
29/12/2022	Material PIP001 - RMC - Gal Steel Post - 50mm NB			
29/12/2022	Plant VMS0001 - RMC - VMS Ute (Dry Hire)			
29/12/2022	Labour TC0002 - RMC - Traffic Controller Only (Penalty)			
29/12/2022	Labour TC0001 - RMC - Traffic Controller Only (Day)			
29/12/2022	Labour 103001 - RMC - 10300 (S or C) - Construction Worker (Day)			
29/12/2022	Labour 103001 - RMC - 10300 (S or C) - Construction Worker (Day)			
29/12/2022	Labour 103001 - RMC - 10300 (S or C) - Construction Worker (Day)			
29/12/2022	Labour 103001 - RMC - 10300 (S or C) - Construction Worker (Day)			



Priority Details	
Priority	9 Alert
Corp. Weighting	-
Field Weighting	-
Road Cat. Score	-
Risk Score	-
Response Time	30 days
Response Due Date	04/01/2023 12:38
Inspection Due Date	05/01/2023 12:38



Released Under RTI

29/12/2022	Labour 103001 - RMC - 10300 (S or C) - Construction Worker (Day)
29/12/2022	Plant TRK0003 - RMC - Truck (Dry Hire) <9.5T pay load
29/12/2022	Plant TMA0001 - RMC - Truck TMA - (Dry Hire)
29/12/2022	Plant TRK0003 - RMC - Truck (Dry Hire) <9.5T pay load
29/12/2022	Plant VMS0002 - RMC - VMS Truck (Dry Hire)



Released under RTI - DTMR

Job 1706550 DEFECT

<input type="checkbox"/> Scheduled	
Priority	10
Due Date	-
Activity	8B42410 - Remove Unauthorised Signs
WBS	1890 - Remove Unauthorised Signs
Comment	Remove 2 unauthorised signs from TMR furniture Beaudesert Nerang rd at Crane cr & Bartlett av.
Stakeholder Req.	-
Schedule	00 - 22/23 SCH M0B
Contract	CN-11008 Yr 4 - GC - Gold Coast RMC 2022/2023
Work Order	WO2354665 - NO NAME <input type="checkbox"/> Expired 15/12/2022 - 16/12/2022
Claim	-
Created	15/12/2022 by dzfinch
Approved	15/12/2022 by dzfinch
Reference	-
Job Type	DEFECT
Source System	AMMS
SIMS Info	
SIMS Number	-
Ready To Claim	optional <input type="checkbox"/> Unpaid

Defect Location	
Road	202 - BEAUDESERT - NERANG ROAD
Chainage	49.09 - 50.67 (1.58 km)
Carriageway	1 - Primary Through Undivided
Lane	0 - All Lanes
Road Tier	5
Road Category	Cat C
Defect Details	
Defect	RE2_S - Litter on road reserve - Schedule with Mowing Category: 400 - Roadside Assets
Size	-
Fault Cause	-
Fault Indication	-
SAP Info	
SAP Ref. ID	-
SAP Network No.	7011210
Claim Details	
Quantity	<input type="checkbox"/> Estimated <input type="checkbox"/> Completed
Amount	<input type="checkbox"/>



Priority Details	
Priority	10 <input type="checkbox"/> Priority
Corp. Weighting	-
Field Weighting	-
Road Cat. Score	-
Risk Score	-
Response Time	-
Response Due Date	-
Inspection Due Date	-




Released under RTI



Released under RTI - DMR

RMC Incident Response

Reference: 752IU240 • Oct 28, 2022, 02:43 PM



Location (Map Center)

-27.999727, 153.296890

Report Generated

Oct 31, 2022, 08:03 AM

Generated by

Jodi Rood


RMC Incident Response

Reference: 752IU240 • Oct 28, 2022, 02:43 PM • Adrian Kels



Photo 1

Oct 28, 2022, 12:38 PM




Longitude -27.999694 Latitude 153.296797
Accuracy 0 m



Photo 2

Oct 28, 2022, 12:38 PM



Longitude -27.999736 Latitude 153.296844
Accuracy 0 m


RMC Incident Response

Reference: 752IU240 • Oct 28, 2022, 02:43 PM • Adrian Kels



Photo 3

Oct 28, 2022, 12:42 PM




Longitude -27.999733 Latitude 153.296814
Accuracy 0 m



Photo 4

Oct 28, 2022, 12:44 PM



Longitude -27.999797 Latitude 153.296814
Accuracy 0 m


RMC Incident Response

Reference: 752IU240 • Oct 28, 2022, 02:43 PM • Adrian Kels



Photo 5

Oct 28, 2022, 01:49 PM




Longitude -27.999828 Latitude 153.296861
Accuracy 0 m



Photo 6

Oct 28, 2022, 01:49 PM



Longitude -27.999756 Latitude 153.296814
Accuracy 0 m

RMC Incident Response

Reference: 752IU240 • Oct 28, 2022, 02:43 PM • Adrian Kels




Photo 7

Oct 28, 2022, 01:49 PM

Longitude -27.999764 Latitude 153.296831
Accuracy 0 m




Photo 8

Oct 28, 2022, 01:49 PM

Longitude -27.999747 Latitude 153.296814
Accuracy 0 m


RMC Incident Response

Reference: 752IU240 • Oct 28, 2022, 02:43 PM • Adrian Kels

Request

Incident Type	Type 3
Time the incident was reported to RoadTek	Oct 28, 2022, 10:54 AM
RoadTek Job No.	1692399
RMC Project No.	7011210
SIMS no.	44962
All responding Crews	Red Crew
Source of Request	SCTMC
Road Number	202
Road Name	Beaudesert-Nerang rd
Start Chainage	47.610

Respond

Site Arrival Time	Oct 28, 2022, 12:30 PM
Weather Conditions	Fine
Material Used	 oldmix (asphalt) coldmix (asphalt)
Total number of TMAs responding to callout	1
Total number of VMS Vehicles responding to callout	1
Total number of Job Trucks responding to callout	2
Total number of Construction Workers responding to the callout	5
Total number of Traffic Control Vehicles responding to the callout	2
Total number of Traffic Controllers responding to the callout	2
Direction	Eastbound
Lanes Affected	LH Shoulder, Left Lane, Centre Lane, Right Lane, RH Shoulder

RMC Incident Response

Reference: 752IU240 • Oct 28, 2022, 02:43 PM • Adrian Kels

Lane Status Stop slow

Is the incident resolved (traffic is returned to normal)? Yes

Resolve

Time the work was completed and departure from the site Oct 28, 2022, 02:00 PM

Photos of the site after completion of work




Time of arrival back to works depot or site Oct 28, 2022, 02:30 PM

Closed Off By (Name of TMC operator) Lachlan

Additional Comments Task 1 - Locate and make safe pothole
Located Beaudesert-Nerang rd, EB lane, prior to bird life court.

RMC Incident Response

Reference: OUE61IU5 • Oct 28, 2022, 08:46 PM



Location (Map Center)
-27.999734, 153.296617

Report Generated
Oct 31, 2022, 08:05 AM

Generated by
Jodi Rood


RMC Incident Response

Reference: OUE61IU5 • Oct 28, 2022, 08:46 PM • Adrian Kels



Photo 1

Oct 28, 2022, 07:56 PM




Longitude -27.999711 Latitude 153.296861
Accuracy 0 m



Photo 2

Oct 28, 2022, 07:56 PM



Longitude -27.999728 Latitude 153.296844
Accuracy 0 m


RMC Incident Response

Reference: OUE61IU5 • Oct 28, 2022, 08:46 PM • Adrian Kels



Photo 3

Oct 28, 2022, 08:01 PM




Longitude -27.999753 Latitude 153.296875
Accuracy 0 m



Photo 4

Oct 28, 2022, 08:01 PM



Longitude -27.999769 Latitude 153.296814
Accuracy 0 m


RMC Incident Response

Reference: OUE61IU5 • Oct 28, 2022, 08:46 PM • Adrian Kels



Photo 5

Oct 28, 2022, 08:28 PM




Longitude -27.999761 Latitude 153.296844
Accuracy 0 m



Photo 6

Oct 28, 2022, 08:28 PM



Longitude -27.999761 Latitude 153.296861
Accuracy 0 m

RMC Incident Response

Reference: OUE61IU5 • Oct 28, 2022, 08:46 PM

Kels

Request

Incident Type

Time the incident was reported to RoadTek

022, 07:15 PM

RoadTek Job No.

RMC Project No.

SIMS no.

All responding Crews

Source of Request

Road Number

Road Name

ert-Nerang rd (Mt Nathan rd)

Start Chainage

End Chainage

Respond

Site Arrival Time

022, 08:00 PM

Weather Conditions

Material Used

 cold mix bags

Total number of TMAs responding to callout

Total number of VMS Vehicles responding to callout

Total number of Job Trucks responding to callout

Total number of Construction Workers responding to the callout

Total number of Traffic Control Vehicles responding to the callout

Total number of Traffic Controllers responding to the callout

Direction

und, Southbound, Eastbound, Westbound

RMC Incident Response

Reference: OUE61IU5 • Oct 28, 2022, 08:46 PM • Adrian Kels

Lanes Affected LH Shoulder, Left Lane, Centre Lane, Right Lane, RH Shoulder

Lane Status Stop slow

Is the incident resolved (traffic is returned to normal)? Yes

Resolve

Time the work was completed and departure from the site Oct 28, 2022, 08:32 PM

Photos of the site after completion of work



Time of arrival back to works depot or site Oct 28, 2022, 08:45 PM

Closed Off By (Name of TMC operator) Paul

Additional Comments Task 5 - Locate and make safe pot hole.
Located EB lane, Beaudesert-Nerang rd prior to Birdlife ct

Notification

CANC Set to Cancelled
11:58 on 19/10/2022
By VEN NR

Completed

Created: 10:55 on 14/06/2021
Completed: 11:58 on 19/10/2022

202 - Beaudesert - Nerang Road

107 - Edge Break in Bitumous Surface

107-10800.11 - M2 - Edge repair

Unsealed shoulder edge deviation from the average existing seal width, 75-100mm

Quantity: 0 of 5 M Completed

Priority: Low

Response Time: 60 Months.

Region: South Coast

Contract: RAMC - Gen 2 - 2019-2024

Council: Gold Coast

Classification: T5

Assigned To: VEN NR

Assigned Date: 10:57 on 14/06/2021

WBS: 700-03690-03-04-03

SAP Work Order Number: 000116932433

Linked Assets:

202_1_47.6_47.7 - 202 - Beaudesert-Nerang Road

Recent Comments:


"Completed works under wo 50876"

VEN NR - 11:58 on 19/10/2022

"CA0621 Edge break needs edge repair approximately 5m"

VEN NR - 10:57 on 14/06/2021

Due by 14/06/2026 on 10:57



Located on Beaudesert - Nerang Road, at Chainage 47606
692m past Beaudesert-Nerang Rd & Pademelton Pass (1 or 2)

GPS: -27.9997912, 153.2967044

Job Data

Job Location	Beaudesert Nerang Road westbound outside Coolibah Downs left hand side		
Claimed			
Future Works	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Take 5 Completed?	<input type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> N/A
Do I have the correct tools/equipment to complete this task?	<input type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> N/A
Do I have the correct PPE to complete this task?	<input type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> N/A
TGS Used			

JDE Code		
Job Type Name	Edge Break/Drop Off	



Released under RTI



Routine Inspection

Completed

Region: South Coast

Scheduled: 11/10/2022 0:00

Contract: RAMC - Gen 2 - 2019-2024

Started: 13/10/2022 10:33

Completed: 13/10/2022 10:33

Assigned To: VEN - [redacted]


Completed By: VEN [redacted]

Asset 202 Beaudesert - Nerang Road C (Road)

Direction Both

From An error has occurred while processing HtmlTextBox 'htmlTextBox12':
An error occurred while parsing EntityName. Line 1, position 29.

To End Road



Located on 202 Beaudesert - Nerang Road C, from Chainage 42320 to 52140
From: 0m past Beaudesert Nerang Rd & Maudsland Road To: 0m past End Road (Both)

Released Under RTMR



Routine Inspection

Completed

Region: South Coast

Contract: RAMC - Gen 2 - 2019-2024

Assigned To: VEN -

Scheduled: 27/09/2022 0:00

Started: 29/09/2022 10:34

Completed: 29/09/2022 10:34


Completed By: VEN

Asset 202 Beaudesert - Nerang Road C (Road)

Direction Both

From An error has occurred while processing HtmlTextBox 'htmlTextBox12':
An error occurred while parsing EntityName. Line 1, position 29.

To End Road



Located on 202 Beaudesert - Nerang Road C, from Chainage 42320 to 52140
From: 0m past Beaudesert Nerang Rd & Maudsland Road To: 0m past End Road (Both)

Released Under RTMR



Routine Inspection

Completed

Region: South Coast

Contract: RAMC - Gen 2 - 2019-2024

Assigned To: VEN - NR

Scheduled: 25/10/2022 0:00

Started: 26/10/2022 13:32

Completed: 26/10/2022 13:50


Completed By: VEN - NR

Asset 202 Beaudesert - Nerang Road C (Road)

Direction Both

From An error has occurred while processing HtmlTextBox 'htmlTextBox12':
An error occurred while parsing EntityName. Line 1, position 29.

To End Road



Located on 202 Beaudesert - Nerang Road C, from Chainage 42320 to 52140
From: 0m past Beaudesert Nerang Rd & Maudsland Road To: 0m past End Road (Both)

Released under RTMR

Hazard (Hazard.18)

REVD Set to Reviewed
15:23 on 14/11/2022
By VEN -

Completed

Created: 14:40 on 28/10/2022
Completed: 16:41 on 02/11/2022

202 - Beaudesert - Nerang Road

104 - Very Rough Surface in Bituminous Surface

Hazard.18 - M2 - Pavement repairs (minor) (10 to 50m2)

Any rough surface with a difference in height, 4m SL, >50mm

Quantity: 2.1 of 2 M3 Completed

Length: 5.000 Width: 4.200 Depth: 0.100

Priority: Low

Response Time: 24 Hours.

Due by 29/10/2022 on 14:40

Region: South Coast

Contract: RAMC - Gen 2 - 2019-2024

Council: Gold Coast

Classification: T5

Assigned To: VEN - Flocon + Plant Required

Assigned Date: 14:40 on 28/10/2022


WBS: 700-03690-03-04-08

SAP Work Order Number: 000117492318

Linked Assets:

202_1_47.6_47.7 - 202 - Beaudesert-Nerang Road

Recent Comments:



Located on Beaudesert - Nerang Road, at Chainage 47620
706m past Beaudesert-Nerang Rd & Pademelton Pass (1 or 2)

GPS: -27.9997407, 153.2968684

"Rough surface patched using ac14
5m x 4.2m

VEN - docket #32403 "
VEN - - 16:41 on 02/11/2022

"Enq no. 4610"

VEN - - 10:12 on 31/10/2022


"Rough surface needs pavement repairs approximately 5m x 3.5m "

VEN - - 14:43 on 28/10/2022

Job Data

Job Location	Beaudesert Nerang Road eastbound approximately 60m west of Crane Creek
Claimed	YES
Future Works	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Have you contacted TMC?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
Take 5 Completed?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A

Do I have the correct tools/equipment to complete this task?	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> N/A	
Do I have the correct PPE to complete this task?	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> N/A	
TGS Used	219 + 300			
Job Notes	November			
Job Type Name	Pavement (Non Pothole)			
Environmental Suitability	Qld Fire Ant Biosecurity Zones			






Released under RTI - DTMR



Released under RTI - DTMR

Hazard (Hazard.11)

REVD Set to Reviewed
14:57 on 14/11/2022
By VEN - 

Completed

Created: 7:25 on 31/10/2022
Completed: 12:08 on 02/11/2022

202 - Beaudesert - Nerang Road

103 - Potholes/Delamination in Bituminous Surface

Hazard.11 - M1 - Pothole Patching (Cold)

Depth of Pothole in a hazardous location, >30mm

Quantity: 1 of 1 Each Completed

Priority: Urgent

Response Time: 24 Hours.

Region: South Coast

Contract: RAMC - Gen 2 - 2019-2024

Council: Gold Coast

Classification: T5

Assigned To: VEN - 

Assigned Date: 7:25 on 31/10/2022


WBS: 700-03690-03-02-01

SAP Work Order Number: 000117494207

Linked Assets:

202_1_47.6_47.7 - 202 - Beaudesert-Nerang Road

Recent Comments:




Located on Beaudesert - Nerang Road, at Chainage 47643
729m past Beaudesert-Nerang Rd & Pademelton Pass (1 or 2)

GPS: -27.9997834, 153.2970968

"1x pothole shove made safe will need permanent repairs"

VEN -  - 14:57 on 14/11/2022

"Completed"

VEN -  - 12:08 on 02/11/2022

"1x pothole shove made safe will need permanent repairs "

VEN -  - 7:31 on 31/10/2022

Job Data

Job Location	Nerang Beaudesert rd at chainage 47643		
Claimed	YES		
Future Works	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Have you contacted TMC?	<input type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> N/A
Take 5 Completed?	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> N/A
Do I have the correct tools/equipment to complete this task?	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> N/A

Do I have the correct PPE to complete this task?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A	
TGS Used	List	
Job Notes		
Job Type Name	Potholes	
Environmental Suitability	Qld Fire Ant Biosecurity Zones	



Released under RTI - DTMR

Hazard (Hazard.15)

REVD Set to Reviewed
15:01 on 14/11/2022
By VEN -

Completed

Created: 9:33 on 31/10/2022
Completed: 5:17 on 03/11/2022

202 - Beaudesert - Nerang Road

302 - Drainage Obstructed

Hazard.15 - M2 - Clean Culverts, Pipes and Pits - Minor

Pipe obstructed, requires CCTV or Jetrodding, flow area is reduced >40%

Quantity: 1 of 1 M Completed

Priority: Low

Response Time: 24 Hours.

Region: South Coast

Contract: RAMC - Gen 2 - 2019-2024

Council: Gold Coast

Classification: T5

Assigned To: VEN - D1 RM

Assigned Date: 9:33 on 31/10/2022

WBS: 700-03690-03-03-15

SAP Work Order Number: 000117495067

Linked Assets:

202_1_47.6_47.7 - 202 - Beaudesert-Nerang Road


Recent Comments:

"Drain cleared of debris "

VEN - 5:17 on 03/11/2022

"Drain blocked and requires clearing.
Hand work "

VEN - 9:36 on 31/10/2022



Located on Beaudesert - Nerang Road, at Chainage 47623
709m past Beaudesert-Nerang Rd & Pademelton Pass (1 or 2)
GPS: -27.9997704, 153.2968919

Job Data

Job Location	Beaudesert Nerang Road at driveway for property 38 end of Kerb		
Claimed	YES		
Future Works	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Have you contacted TMC?	<input type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> N/A
Take 5 Completed?	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> N/A
Do I have the correct tools/equipment to complete this task?	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> N/A
Do I have the correct PPE to complete this task?	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> N/A

TGS Used	List	
Job Notes		
Job Type Name	Drainage	
Environmental Suitability	Qld Fire Ant Biosecurity Zones	



Released under RTI - DTMR



Routine Inspection

Completed

Region: South Coast

Scheduled: 09/11/2022 0:00

Contract: RAMC - Gen 2 - 2019-2024

Started: 08/11/2022 8:17

Assigned To: VEN -

Completed: 09/11/2022 6:25


Completed By: VEN -

Asset 202 Beaudesert - Nerang Road C (Road)

Direction Both

From An error has occurred while processing HtmlTextBox 'htmlTextBox12':
An error occurred while parsing EntityName. Line 1, position 29.

To End Road



Located on 202 Beaudesert - Nerang Road C, from Chainage 42320 to 52140
From: 0m past Beaudesert Nerang Rd & Maudsland Road To: 0m past End Road (Both)

Job ID	Activity	Location	Creation	Chainage	Quantity	Assigned	Status
54747	103-10500 (2)	623m past Edsrt Nerang Rd & Crystal Springs & Venn	08/11/2022 10:2	1 or 2 43,343	<input type="text" value="NR"/>	VEN - D RM	COMPLETE
54748	103-10500 (2)	514m past Bdsrt Nerang Rd & Crystal Springs & Venn	08/11/2022 10:2	1 or 2 43,234	<input type="text" value="NR"/>	VEN - D RM	COMPLETE
54749	103-10500 (2)	983m past Bdsrt Nerang Rd & Crystal Springs & Venn	08/11/2022 10:3	1 or 2 43,703	<input type="text" value="NR"/>	VEN - D RM	COMPLETE



Routine Inspection

Completed

Region: South Coast

Scheduled: 23/11/2022 0:00

Started: 23/11/2022 11:58

Contract: RAMC - Gen 2 - 2019-2024

Completed: 23/11/2022 14:12

Assigned To: VEN - NR


Completed By: VEN - NR

Asset 202 Beaudesert - Nerang Road C (Road)

Direction Both

From An error has occurred while processing HtmlTextBox 'htmlTextBox12':
An error occurred while parsing EntityName. Line 1, position 29.

To End Road



Located on 202 Beaudesert - Nerang Road C, from Chainage 42320 to 52140
From: 0m past Beaudesert Nerang Rd & Maudsland Road To: 0m past End Road (Both)

Job ID	Activity	Location	Creation	Chainage	Quantity	Assigned	Status
57787	103-10500 (2)	48,024m past Start Road	23/11/2022 13:4	3 48,024	NR	VEN - D RM	COMPLETE
57788	104-17021 (22)	48,024m past Start Road	23/11/2022 13:5	3 48,024	NR	VEN - 2 Backlog	OPEN
57789	103-10500 (2)	39m past Beaudesert-Nerang Rd & Birdlife Crt	23/11/2022 13:5	1 or 2 47,913	NR	VEN - D RM	COMPLETE
57790	105-15841 (3)	1m past Beaudesert-Nerang Rd & Birdlife Crt	23/11/2022 13:5	1 or 2 47,875	NR	VEN - 2 Backlog	OPEN



Jobs Export

50876	TS	Road	202	Beaudesert - Nerang Road	1 or 2	47605	Beaudesert Nerang Road westbound and eastbound approximately 40m west of Crane Creek	104-17041	Very Rough Surface in Bituminous Surface	M3 - Pavement repairs (minor) (>50m2)	NR	2 patches completed with 51.8tonne of ac14 (320 and 119ltrs of emulsion for a total of 199.3m2 and 21.58m3	30/09/2022 13:05	11/10/2022 4:20	Pavement (Non Pothole)	Complete	Hazard
50877	TS	Road	202	Beaudesert - Nerang Road	1 or 2	47605	Beaudesert Nerang Road eastbound approximately 40m west of Crane Creek	103-10500	Potholes/Delamination in Bituminous Surface	M1 - Pothole Patching (Cold)	NR	6x potholes patched	30/09/2022 13:08	04/10/2022 10:57	Potholes	Complete	Safety
22621	TS	Road	202	Beaudesert - Nerang Road	1 or 2	47606	Beaudesert Nerang Road westbound outside Coolibah Downs left hand side	107-10800	Edge Break in Bitumous Surface	M2 - Edge repair	NR	Completed works under wo 50876 Rough surface patched using ac14 5m x 4.2m	14/06/2021 10:55	19/10/2022 11:58	Edge Break/Drop Off	No Action Required	Notification
52605	TS	Road	202	Beaudesert - Nerang Road	1 or 2	47620	Beaudesert Nerang Road eastbound approximately 60m west of Crane Creek	104-17031	Very Rough Surface in Bituminous Surface	M2 - Pavement repairs (minor) (10 to 50m2)	NR	6.10 tonne (austek) docket #32403	28/10/2022 14:00	02/11/2022 16:41	Pavement (Non Pothole)	Complete	Hazard
53255	TS	Road	202	Beaudesert - Nerang Road	1 or 2	47623	Beaudesert Nerang Road at driveway for property 38 end of Kerb	302-33400	Drainage Obstructed	M2 - Clean Culverts, Pipes and Pits - Minor	NR	Drain cleared of debris	31/10/2022 9:33	03/11/2022 5:17	Drainage	Complete	Hazard
53238	TS	Road	202	Beaudesert - Nerang Road	1 or 2	47643	Nerang Beaudesert rd at chainage 47643	103-10500	Potholes/Delamination in Bituminous Surface	M1 - Pothole Patching (Cold)	NR	1x pothole shove made safe will need permanent repairs	21/10/2022 7:25	02/11/2022 12:08	Potholes	Complete	Hazard

Released under RTI - [REDACTED]



Road Inspections Export

ASSET VISION®

Inspection ID	Road Code	Inspection Type	Road Name	Start Date	Completed Date	Entire Length	Status	Comments	Jobs
47751	202	Routine Inspection	Beaudesert - Nerang Road	29/09/2022 10:34	29/09/2022 10:34	Yes	Completed		0
47316	202	Routine Inspection	Beaudesert - Nerang Road	13/10/2022 10:33	13/10/2022 10:33	Yes	Completed		0
47757	202	Routine Inspection	Beaudesert - Nerang Road	26/10/2022 13:32	26/10/2022 13:50	Yes	Completed		0
57436	202	Routine Inspection	Beaudesert - Nerang Road	08/11/2022 8:17	09/11/2022 6:25	Yes	Completed		3
59464	202	Routine Inspection	Beaudesert - Nerang Road	23/11/2022 11:58	23/11/2022 14:12	Yes	Completed		4

Released under RTI - DTMR